



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representative	es ^D iesent During the Inspection:	
Company	JD Leonard	
OGM	Steve Demozak	_

Inspection Report

Permit Number:	C0070041		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, April 24, 2012		
Start Date/Time:	4/24/2012 10:00:00 AM		
End Date/Time:	4/24/2012 1:00:00 PM		
Last Inspection:	Wednesday, March 21, 2012		

Inspector: Steve Demczak,
Weather: Sunny, 50's, Muddy
InspectionID Report Number: 3087

Amented by

Permitee: WEST RIDGE RESOURCES
Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

	Current Acreages		Mineral Ownership	Types of Operations
	7,600.38	Total Permitted	☑ Federal	☑ Underground
	30.99	Total Disturbed	☑ State	Surface
		Phase I	☐ County	☐ Loadout
		Phase II	☐ Fee	☐ Processing
		Phase III	☐ Other	Reprocessing
Report summar	y and status fo	or pending enforcen	nent actions, permit conditions,	Division Orders, and amendments:

The Permittee continues to meet this Special Condition of the current State of Utah permit to send water data

electronically.

Inspector's Signature:

Steve Demczak,

Inspector ID Number: 39

Date

Tuesday, May



Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 24, 2012

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.
- Evaluated Not Applicable Comment Enforcement Permits, Change, Transfer, Renewal, Sale П Signs and Markers Ø Topsoil 4.a Hydrologic Balance: Diversions V V 4.b Hydrologic Balance: Sediment Ponds and Impoundments 4.c Hydrologic Balance: Other Sediment Control Measures П 4.d Hydrologic Balance: Water Monitoring 4.e Hydrologic Balance: Effluent Limitations Disposal of Excess Spoil, Fills, Benches Coal Mine Waste, Refuse Piles, Impoundments Noncoal Waste Ø Ø Protection of Fish, Wildlife and Related Environmental Issues 10. Slides and Other Damage \mathbf{Z} Ø 11. Contemporaneou s Reclamation 12. Backfilling And Grading 13. Revegetation 14. Subsidence Control \mathbf{Z} \square 15. Cessation of Operations $\overline{\Box}$ 16.a Roads: Construction, Maintenance, Surfacing 16.b Roads: Drainage Controls \square Ø 17. Other Transportation Facilities 18. Support Facilities, Utility Installations П 19. AVS Check $\overline{\Box}$ 20. Air Quality Permit 21. Bonding and Insurance 22. Other

Inspection Continuation Sheet

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 24, 2012

Page 3 of 3

2. Signs and Markers

The identification sign is after the main gate to the property. All information complied with the R645 Coal Rules.

4.a Hydrologic Balance: Diversions

Diversions were opened and functioning as designed. Some of the diversions will need to be cleaned out in the near future. Sediment has started to build-up in some of the diversions and culverts. Currently the diversions are functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was inspected and contained a small amount of water. No hazardous conditions were noticed during the inspection.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

14. Subsidence Control

Subsidence information is in the annual report.

16.b Roads: Drainage Controls

Road drainage was functioning as designed.